



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
June 24, 2005

Supervisor ADZ

**Mine Name:** Skyline Pine Quarry  
**Operator Name:** Rosco Ward

**Permit number:** S/003/040  
**Inspection Date:** June 15, 2005  
**Time:** 9:00 am

**Inspector(s):** Lynn Kunzler  
**Other Participants:** Rosco Ward  
**Mine Status:** inactive

**Weather:**

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

Operator requested inspection prior to pending transfer

**Inspection Summary:**

12. While we were able to drive to the site, there was still significant snow drifts which prevented us from reviewing the site. We will need to revisit this site in 2-3 weeks.

**Directions to Site:** This site is located on the ridge above Bonneville Quarries, Inc.'s Grouse Creek Mountain Quarry.

**Inspector's Signature**

Dawn Haddock  
for Lynn Kunzler

**Date:** June 24, 2005

LK:jb

O:\M003-BoxElder\S0030040-SkylinePine\inspections\insp-06152005a.doc